

TOOLS FOR HUBER+SUHNER QUICK-FIT[®] CONNECTORS

cable stripping tools for easy cable preparation
in one single operation
(can be used manually or with electrical power tool)



H+S type	Item no.	Cable type	Assembly instructions
74_Z-0-8-15	23000296	3/8": Andrew LDF 2-50	0000180713
74_Z-0-9-15	23001006	1/2" Highflex: SUCOFEED [®] , Andrew, NK cables, RFS (Kabelmetal)	0000179418/ 0000201603
74_Z-0-12-15	23000319	1/2": SUCOFEED [®] , Andrew, NK cables, RFS (Kabelmetal)	0000179113
74_Z-0-23-16	23007928	7/8": SUCOFEED [®] , Andrew, NK cables, RFS (Kabelmetal) 7/8" Highflex: SUCOFEED [®] , Andrew	0000180164/ 0000201645 0000233737
74_Z-0-23-17	84017918	7/8" Low attenuation: SUCOFEED [®] , Andrew	0000243692/0000236366
74_Z-0-32-14	23010533	1 1/4": SUCOFEED [®] , Andrew, NK cables, RFS (Kabelmetal)	0000179128
74_Z-0-42-14	23010534	1 5/8": SUCOFEED [®] , Andrew, NK cables, RFS (Kabelmetal)	0000179128

HUBER+SUHNER[®] QUICK-FIT installation kit

Tool kit for all QUICK-FIT Connectors
(with additional space for other auxiliary tools and spare parts)

Stripping tools can be accommodated but are not included



H+S type	Item no.	Description	Content	Size
74_Z-0-0-600	23002174	tool box	all tools of the following table marked with *	620 × 430 × 140 mm/ 24.4 × 17 × 1.5 in.

Overview necessary tools for the assembly of QUICK-FIT connectors

H+S type	Item no.	Part description	Corrugated copper tube cables							
			$\frac{3}{8}$ " LFD 2-50	$\frac{1}{2}$ " HF	$\frac{1}{2}$ "	$\frac{7}{8}$ "	$\frac{7}{8}$ " HF	$\frac{7}{8}$ " LA	$1 \frac{1}{4}$ "	$1 \frac{5}{8}$ "
74_Z-0-8-15	23000296	stripping tool ($\frac{3}{8}$ " LFD 2-50)	X							
74_Z-0-9-15	23001006	stripping tool ($\frac{1}{2}$ " HF)		X						
74_Z-0-12-15	23000319	stripping tool ($\frac{1}{2}$ "			X					
74_Z-0-23-16	23007928	stripping tool ($\frac{7}{8}$ " + $\frac{7}{8}$ " HF)				optional	optional			
74_Z-0-23-17	84017918	stripping tool ($\frac{7}{8}$ " LA)						optional		
74_Z-0-32-14	23010533	stripping tool ($1 \frac{1}{4}$ "							optional	
74_Z-0-42-14	23010534	stripping tool ($1 \frac{5}{8}$ "								optional
74_Z-0-0-359	23014976	handle (for stripping tools)	X ⁴⁾	X ⁴⁾	X ⁴⁾	optional	optional	optional	optional	optional
74_Z-0-0-402	22652193	* abrasive paper 320	X	X	X					
74_Z-0-0-424	23001952	* spanner AF 17 mm	X							
74_Z-0-0-425	23001953	* spanner AF 18 mm	X							
74_Z-0-0-426	23001954	* spanner AF 19 mm	X							
74_Z-0-0-427	23001955	* spanner AF 21 mm	X	X						
74_Z-0-0-428	23001956	* spanner AF 22 mm		X	X					
74_Z-0-0-429	23001957	* spanner AF 24 mm			X					
74_Z-0-0-430	23001958	* spanner AF 30 mm				X	X	X		
74_Z-0-0-431	23001959	* spanner AF 36 mm				X	X	X		
74_Z-0-0-415	22652206	* counter sink				X ¹⁾	X ¹⁾	X ¹⁾	X ¹⁾	X ¹⁾
74_Z-0-0-418	22652209	* Stanley knife	X	X	X	X	X	X	X	X
74_Z-0-0-420	22652211	* steel brush			X	X	X	X	X	X
74_Z-0-0-422	22652213	* steel measure 200 mm	X ²⁾	X ²⁾	X ²⁾	X ²⁾	X ²⁾	X ²⁾	X ²⁾	X ²⁾
74_Z-0-0-432	23002005	* screw driver (2)	X		X					
74_Z-0-0-433	23002007	* screw driver (4)				X	X	X	X	X
74_Z-0-0-12	22642718	small metal saw	X	X	X	X	X	X	X	X
74_Z-0-0-434	23002166	monkey wrench ³⁾ (min. 65mm)							X	X
		small file	X ²⁾	X ²⁾	X ²⁾					

* = tools included in the HUBER+SUHNER QUICK-FIT installation kit 74_Z-0-0-600, (can be ordered with item no. 23002174)

- 1) for assembly use either the Stanley knife or the counter sink
- 2) only necessary without HUBER+SUHNER stripping tool
- 3) 2 wrenches are needed for assembling
- 4) handle included in QUICK-FIT stripping tool delivery

Spare parts for QUICK-FIT cable stripping tools



H+S type	Item no.	Description	Application	Function
74_Z-0-0-346	23000936	blade	74_Z-0-8-15 74_Z-0-8-16 74_Z-0-9-15 74_Z-0-12-15	stripping jacket
74_Z-0-0-347	23000937	blade	74_Z-0-8-15 74_Z-0-8-16 74_Z-0-12-15	cutting corrugated copper tube
74_Z-0-0-348	23000938	triangle knife	74_Z-0-8-15 74_Z-0-8-16 74_Z-0-9-15 74_Z-0-12-15	deburring inner conductor
74_Z-0-0-349	23001008	blade	74_Z-0-9-15	cutting corrugated copper tube
74_Z-0-0-297	22650531	blade	74_Z-0-23-16 74_Z-0-23-17	cutting corrugated copper, foam and inner conductor
74_Z-0-0-355	23008264	blade	74_Z-0-23-16 74_Z-0-32-14 74_Z-0-32-17	stripping jacket
74_Z-0-0-356	23010537	blade	74_Z-0-42-14	stripping jacket

Additional tools for HUBER+SUHNER® QUICK-FIT cable stripping tools

H+S type	Item no.	Tool description	Function
74_Z-0-0-416	22652207	* allen wrench AF 2.5 mm/.098 in.	spare blades for the stripping tools 74_Z-0-8-15, 74_Z-0-8-16, 74_Z-0-9-15, 74_Z-0-12-15, 74_Z-0-23-16, 74_Z-0-23-17, 74_Z-0-32-14 and 74_Z-0-42-14
74_Z-0-0-423	23000311	* allen wrench AF 4 mm/.157 in.	for removing the BIT adaptor
74_Z-0-0-421	22652212	* screwdriver, Torx 1 (Torx T7)	for changing the triangle knife 74_Z-0-0-348

* = not included in the HUBER+SUHNER QUICK-FIT installation kit 74_Z-0-0-600